



Figure 12c-02. Hydrologic model in fractured crystalline bedrock. Colorado Geological Survey ON-010 Colorado Groundwater Atlas.